Lead and Asbestos Survey and Sampling Reports and Letter (Scott Lawson Group, 1999)

October 14, 1999

Mr. Joseph Griffiths Hill Mill Realty 428 Central Street Franklin, New Hampshire 03235

Re:

Asbestos and Lead Survey at former Beck Woolen Mill

SLGL File Number 990666

Dear Mr. Griffiths:

#### **EXECUTIVE SUMMARY**

On September 28, 1999, an Asbestos and Lead Survey was performed by Health and Safety (H&S) Professionals with *The Scott Lawson Group, Ltd. (SLGL)*. The inspection was performed at the former Beck Woolen Mill located on West Mill Street in Hillsborough, New Hampshire. Included with this report are the analytical results of all bulk samples collected during the inspection, a discussion of the findings of the inspection, recommendations, and general cost estimates for abatement or disposal. Final report review was conducted by Gregory Stevenson, Director of Technical Services.

Asbestos-Containing Building Materials (ACBM) were identified in the form of thermal system insulation, roofing materials, electrical insulation paper, cement board panels, and window glazing. Lead-Based Paint (LBP) was identified on most exterior surfaces and in the interior of the Main Mill building. The analytical results can be found in Appendices A, B and C.

Asbestos-Containing Materials (ACM) must be abated prior to activities such as renovation or demolition, which may disturb the materials. Due to the presence of LBP, demolition and disposal of certain building materials must be performed in accordance with Federal and State regulations.

#### DISCUSSION

The buildings at the former Beck Woolen Mill site are generally of wooden post and beam construction. The Main Mill is a three-story structure with a large Boiler Room. Most interior walls, floors and ceilings are wood or wood panels, with fiberglass insulation above ceilings and behind walls in some locations. The western end of the Main Mill building has already been partially demolished, and there are large debris piles along the south side of the Main Mill building as well.

#### Asbestos

A walkthrough was first conducted on each floor and area of the Main Mill and Storage Building with suspect ACM being categorized into homogeneous groups, as needed. Forty (40) samples were collected throughout the two buildings and analyzed for Asbestos content. The following table lists the location, quantity, and general condition of the ACBM identified at the former Beck Woolen Mill site.

#### Main Mill Building

Location	ACM	Approximate Quantity	General Condition
Second floor, north side around electrical boxes	White Insulation Paper	70 ft²	Fair-Poor
Main Roof	Roofing Material and flashing tar	13,300 ft²	Fair
Front Overhang, in debris pile	Roof Flashing tar	160 ft²	Fair
Boiler Room	Thermal System Insulation, including boiler, breeching and tank insulation	1	Fair-Poor
Boiler Room Roof	Roofing Material and flashing tar	1	Fair

Square feet =  $ft^2$ 

1 - These materials were not quantified at the time of the survey. Plans for this area of the Main Mill do not include demolition.

The Storage Building at the Beck Woolen Mill site is located to the east of the Main Mill Building. Part of the western end of the building has been burned and debris from the roof has collapsed into the building interior.

#### Storage Building

Location	ACM	Approximate Quantity	General Condition
Walls and Ceilings in center area	Cement Board Panels (also known as Transite®) 2	2,185 ft²	Fair
Main Roof and debris in burned section	Roofing Material	3,500 ft <sup>2</sup>	Fair-Poor
Along river side of building	Window Glazing	10 windows (3' x 5' each)	Fair

Square feet =  $ft^2$ 

2 Cement board panels are presumed to be ACM, based on the experience of the Inspector, and appearance of the materials. No samples were collected of this material.

#### Lead-Based Paint

Demolition or renovation activities (or maintenance actions) which may disturb or dislocate LBP may cause Lead-containing dust particulate to be released into the atmosphere, thereby creating a potential health hazard to workers, building occupants, and public in the vicinity. Contractors performing work, which may disturb LBP, should apprise all of his or her workers, supervisory personnel, and Subcontractors who shall be on the job site of the seriousness of the health hazards and proper work procedures, which must be followed. Health hazards related to exposure to Lead generally affect infants, children under the age of 7 years old, and women of childbearing age. Risks to children include damage or potential damage of the brain and central nervous system. Recent studies on middle-aged adult males have indicated a relationship between exposure to Lead and high blood pressure, as well as reproductive hazards to both men and women.

In addition to the bulk samples collected of suspect ACM, SLGL collected five (5) paint chip samples for Lead. Three (3) of the samples exceeded the State of New Hampshire and the U.S. Housing and Urban Development (HUD\*) guideline for Lead of 0.5 percent (0.5%). Concentrations in these three (3) samples ranged from 1.0% to 6.1% (See Appendix B).

\* HUD - U.S. Housing and Urban Development. This guideline is used to determine whether Lead is present in paint at a concentration that may be of concern to building occupants, particularly infants or young children. From an OSHA compliance aspect, it is not necessarily the concentration of Lead present in the sample that is of concern, but the concentration that may be rendered airborne during renovation or demolition activities, exposing the general public, workers and building occupants to Lead.

Location of LBP	Paint Color	a
Exterior of Main Mill and Storage Building	Red	
Main Mill, interior walls in Boiler Room	Brown/Black	
Main Mill, interior walls and beams	Dark Green	

In addition to the paint chip samples, *SLGL* collected one composite sample of the exterior clapboard siding that was scheduled to be disposed of as construction debris. The sample was analyzed according to the Toxicity Characteristic Leachate Procedure (TCLP) to determine hazardous waste content, and to determine if the materials exceed the Resource Conservation and Recovery Act (RCRA) disposal guidelines for Lead.

The TCLP results, 115 milligrams of Lead per liter (115 mg/L), showed the siding material exceeds the regulatory limit for Lead of 5.0 mg/L. Therefore, the siding material, if disposed of by itself, cannot be disposed of as regular construction debris. See Appendix C for TCLP results.

# ABATEMENT COST ESTIMATES

ACM must be removed prior to demolition of a building or if it will be disturbed during a renovation project. Much of the ACM identified at the former Beck Woolen Mill site, particularly in the Boiler Room, is in poor condition. Asbestos abatement of any kind is highly regulated, by State and Federal agencies, and must only be performed by trained and licensed personnel.

The cost estimates provided should only be used as a preliminary budget figure. Costs associated with any Asbestos removal project can vary greatly depending on the amount, location, and how much an abatement contractor wants the job. The following table lists the estimated abatement costs, for abatement contractors only, for the removal and disposal of the ACM based on average costs from similar type projects we have managed.

Location	Material	Estimated Abatement Cost
Main Mill Building	Roofing Materials and flashing tar	\$27,000.00 to \$53,850.00
Main Mill Building	Electrical Insulation Paper	\$500.00
Storage Building	Cement Board Panels	\$4,400.00 to \$7,000.00
Storage Building	Roofing Materials	\$7,000.00 to \$14,000.00
Storage Building	Window Glazing	\$400.00 to \$500.00

Total estimated cost for the removal of all ACM in the Main Mill Building is: \$27,500.00 to \$54,350.00

Total estimated cost for the removal of all ACM in the Storage Building is: \$11,800.00 to \$21,500.00

#### CONCLUSION

ACM and LBP have been identified at the former Beck Woolen Mill, both in the Main Mill and the Storage Building. Asbestos was identified in the form of thermal system insulation, roofing materials, electrical insulation paper, cement board panels, and window glazing. LBP was identified on most exterior surfaces and in the interior of the Main Mill building. Laboratory analytical results for all samples collected during the survey can be found in Appendices A, B and C. Abatement cost estimates have been provided in the previous section. These abatement costs are preliminary budget figures only, actual abatement costs will vary.

#### RECOMMENDATION

Based on the results of the survey, SLGL has the following general recommendations:

- State of New Hampshire and Federal regulations require the removal of ACM prior to demolition, or if the ACM is directly impacted by renovation or refurbishing activities. Asbestos removal operations may only be conducted by trained and accredited personnel in accordance with State and Federal regulations. The abatement of exterior ACM/ACBM is regulated by New Hampshire Department of Environmental Services regulations; typically a Site Safety Plan detailing abatement and air monitoring methods are required.
- Hill Mill Realty should consider selective resampling and analysis of demolition debris for Lead by TCLP. The additional samples should include composite (mixed together) samples of all types of demolition debris that will be sent out for disposal, not just the clapboard siding. In the absence of the additional sampling, the red painted clapboard siding must be disposed of as hazardous waste.
- OSHA standards 29 CFR § 1910.1001, Asbestos, 29 CFR § 1910.1025 Lead and 29 CFR § 1910.1200, Hazard Communication, contain requirements for informing employees and building occupants of the presence of hazardous materials such as Asbestos and Lead, along with providing them information on health effects and preventative measures.

We trust you will find everything in order; however, should you have any questions or comments regarding the contents of this report, the inspection, analytical results or project design/air monitoring services, please contact either Matt Comai, Client Services; or me at your earliest convenience.

Sincerely,

The Scott Lawson Group, Ltd.

Richard Lent

Health and Safety Professional

Enclosure

SLGL Data :99Reports:Hill Mill Realty, Mill Survey Final Report (DL)

#### WARRANTY

The conclusions and recommendations contained in this report are based on the information available to SLGL as of September 28, 1999. SLGL provides no warranties on information provided by third parties and contained herein. Data compiled were in accordance with SLGL's approved scope of services and should not be construed beyond their limitations. Any interpretations or use of this report other than those expressed herein are not warranted. The use, partial use, or duplication of this report without the expressed written consent of *The Scott Lawson Group, Ltd.*, is strictly prohibited.

# APPENDIX A

BULK SAMPLE ANALYSIS RESULTS - ASBESTOS

The Sc Lawson Group, Ltd. Environmental, Health & Safety Consultants

Report Prepared For:

428 Central Street Franklin NH 03235 Hill Mill Realty

29 River Road, Suite 18 (800) 645-7674 FAX (603) 228-3871 Bow, NH 03304

October 8, 1999 999066 Report Date SLGL Job#

September 28, 1999 9/28/99 Date Sampled Date Received

RAL Sampler

Beck Woolen Mill Client Project

Analyte : PLM/DS

3											The state of the s		
1010			Obvious	- 11			- Asbestos %		0	Other Fibrous Material %	: Material 9		1
SECE Lab#	Sample Description	Homogeneous Layers Fibrous	is Layers	Fibrous	Color	Chrysotile	Amosite	Chrysotile Amosite Crocidolite	Fibrous	Fibrous Glass Collubora Sumbodia Out.	Sumbleadia		Non Fibrous
135471	092899-666-B01A, Black Flooring Paper, 1st No Floor	No	Yes	Yes	Yes Yes Black, Brown			1	Sep !	60	synunctic 	\	>39
135472	092899-666-B01B, Black Flooring Paper, 2nd Floor	Š	Yes	Yes	Black, Brown	;	1 1 1	!	;	09	2	2	36
135473	092899-666-B01C, Black Flooring Paper, 3rd Floor	Š	Yes	Yes	Black, Brown		;	1 1 1	1 1 2 1	09	!	· ·	>39
135474	092899-666-B02A, Window Glazing, 1st Floor, River Side	%	Yes	Yes	Yes Cream, Brown, Green	1	1	ļ	-	$\overline{\vee}$	l	$\overline{\vee}$	86<
135475	092899-666-B02B, Window Glazing, 3rd Floor, River Side	No	Yes	Yes	Cream, Brown, Green, Black	ļ	! ! !	;		$\overline{\vee}$	! !	-	66<
135476	092899-666-B02C, Window Glazing, 3rd Floor, River Side	No.	Yes	Yes	Cream, Green, Brown		1	!	!	$\overline{\vee}$		$\overline{\vee}$	86<

This Polarized Light Microscopy report relates only to items tested. Client should not use the NVLAP to claim endorsement. PLM by visual area estimation can produce errors of 10%. Results near the 1% level can be more accurately quantified by the point count method or Transmission Electron Microscopy. SLGL laboratory certifications apply only to samples analyzed in-house.

NVLAP Accrediatation Number 101228 Analytical Methodology: 600/R-93/116 July 1993

TTP = Test Till Positive

er Scott, Lab Manager CHRonald By Sabin Analyzed By : -Approved By:

The Sc : Lawson Group, Ltd. Environmental, Health & Safety Consultants

29 River Road, Suite 18 Bow, NH 03304 (800) 645-7674 FAX (603) 228-3871

Franklin NH 03235

Hill Mill Realty 428 Central Street

Report Prepared For:

October 12, 1999 Report Date:

999066 9/28/99 SLGL Job# Date Sampled

September 28, 1999 RAL Sampler Date Received

Beck Woolen Mill Client Project

Analyte : PLM/DS

								-					
SLGL Lab#	Samile Decription		Obvious	s			- Asbestos %			Other Fibrous Material %	s Material	%	i
	Complex Description	Homogeneous Layers Fibrous	us Layers	Fibrous	Color	Chrysotile	Amosite	Chrysotile Amosite Crocidolite	Fibrous	- 1			Non Fibrou
135477	092899-666-B03A, Insulation Paner 2nd	N		1		2000	THE COLUMN	CIOCIONIIIC	Class	Cellulose Synthetic Other	Synthetic	Other	Material
	Floor, Electrical Cabinets	0 0 0 0	res	Y es	res res Lt. Gray, Brown	70		!	!	$\overline{\vee}$	!	1	>29
135478	092899-666-B03B, Insulation Paper, 2nd Floor, Electrical Cabinets	No	Yes	Yes		40	ļ	1	1	20	3	ł	37
125170					Olecii, Oray								
1334/9	092899-666-B04A, Pipe Wrap, 3rd Floor, Stairwell	No	Yes	Yes	Dk. Brown,	;	-	į	40	!	:	40	20
125400					Drown								
004001	092899-666-B04B, Pipe Wrap, 2nd Floor, Stairwell	No	Yes	Yes	Dk. Brown,	1	!	2 2 2	1	$\overline{\vee}$	1	70	>29
135481	5 1300 222 000000				Oray								
1010	692699-000-B03A, Ceiling Panels (Gray), 1st Floor, River Side	o No	Yes	Yes	Gray, Brown,	1	1 1	i	;	06	1	1	10
135482	092899-666-R05R Cailing Dans 1	;			1 1 1 1								
	1st Floor, River Side	No No	Yes	Yes	Gray, Brown,	;	-	1	-	06	!	-	10

produce errors of 10%. Results near the 1% level can be more accurately quantified by the point count method or Transmission Electron Microscopy. SLGL laboratory certifications apply only to samples analyzed in-house. This Polarized Light Microscopy report relates only to items tested. Client should not use the NVLAP to claim endorsement. PLM by visual area estimation can

NVLAP Accrediatation Number 101228 Analytical Methodology: 600/R-93/116 July 1993

TTP = Test Till Positive

Comald BASabin Analyzed By : . Approved By:

The Sc Lawson Group, Ltd. Environmental, Health & Safety Consultants

Report Prepared For:

Franklin NH 03235 Hill Mill Realty 428 Central Street

29 River Road, Suite 18

FAX (603) 228-3871 Bow, NH 03304 (800) 645-7674

October 8, 1999 Report Date

999066 9/28/99 SLGL Job# Date Sampled

September 28, 1999 RAL Sampler Date Received

Beck Woolen Mill Client Project

Analyte : PLM/DS

SLGL Lab#	Sample Description		Obvious	s			- Asbestos %	9		Other Fibrous Material %	s Material	- %	1
201701	International Property of the	Homogeneous Layers Fibrous Color	us Layers	Fibrous	Color	Chrysotile	Amocito	Chrysotile Amoeira Crosidalita	<u> </u>	:			Non Fibrous
135483	092899-666-B05C. Ceiling Panels (Gray,)	N	;	;		Cill Jacune	DIROUIC	Crocidonite	Class	Cellulose Synthetic Other	Synthetic	Other	Material
	Basement (Clay),	o Z	Yes	Yes	Yes Yes Gray, Brown,		!	:	!	06	į		10
135484	092899-666-B06A, Ceiling Panels (Brown), 1st Floor, River Side	Š	Yes	Yes	Brown, Dk.	I	1	! ! !	:	06	1	!	01
135485	092899-666-B06B, Ceiling Panels (Brown), 1st Floor, River Side	No	Yes	Yes	Brown, Black	1	ļ	1	1	06	_	2	7
135486	092899-666-B07, Thermal System Debris, Basement, Boiler Room, on Ground	No	Yes	Yes	Yes Yes Gray, Black	40	l	;	5	!	!	1	55
135487	092899-666-B08, Tank Insulation, Basement, Water Tank	No	Yes	Yes	Yes Yes Lt. Gray, Gray	50		1	$\overline{\vee}$	!	;	1	>49
135488	092899-666-B09, Breeching Insulation, Boiler Room, Upper Level	No	Yes	Yes	Yes Cream, Gray	30	į	1	20	1	į	-	50

produce errors of 10%. Results near the 1% level can be more accurately quantified This Polarized Light Microscopy report relates only to items tested. Client should not use the NVLAP to claim endorsement. PLM by visual area estimation can by the point count method or Transmission Electron Microscopy. SLGL laboratory certifications apply only to samples analyzed in-house.

NVLAP Accrediatation Number 101228 Analytical Methodology: 600/R-93/116 July 1993

TTP = Test Till Positive

ott, Lab Manager E-Ronald B. Sabin Analyzed By: -Approved By:

The Scc Lawson Group, Ltd.
Environmental, Health & Safety Consultants

Report Prepared For:

428 Central Street Franklin NH 03235 Hill Mill Realty

29 River Road, Suite 18 Bow, NH 03304 (800) 645-7674 FAX (603) 228-3871

October 8, 1999 Report Date: SLGL Job#

September 28, 1999 999066 9/28/99 Date Sampled Date Received

RAL Sampler

Beck Woolen Mill Client Project

Analyte : PLM/DS

	Non Fibrous	Material	>93	573	0	20	0	27	0	845	00	>58	
			7	į	ii;			;				_	
Other Fibrous Material % -		Cellulose Synthetic Other	-	;				!		-		· -	
ibrous M		ose syn	i			;		;		V		V	
Other F	S		7	25		5		7		25		40	
=	FIbrous	Olass		$\overline{\vee}$		!		30		5		1	
	Crocidolity			l		ł		!		!		:	
- Asbestos % -	Amosite			-		!		!		i		!	
	Chrysotile Amosite Crocidolite	5		$\overline{\vee}$		10		1		$\overline{\vee}$		!	
	Color	Yes Yes Black, Brown		Black, Gray		Black, Cream,	wnite	Black, Gray		Black, Gray		Yes Black, Brown	
	Fibrous	Yes		Yes		Yes		Yes		Yes	;	Yes	
Obvious	is Layers	Yes		Yes		Yes	į	Yes	;	Yes	;	Yes	
Jones	nomogeneous Layers Fibrous	No	;	o N	;	o N	;	o N	;	o N	7	O Z	
Sample Description		Room Roof, Bottom Laver	092899-666-B11. Roofing Material Bell	Room Roof, Top Layer	092899-666-B12. Roofing Material Beile	Room Roof, Flashing Tar	092899-666-B13. Roofing Material Main	Roof, Center Ridge, Top Layer	092899-666-B14, Roofing Material Main	Roof, Center Ridge, Bottom Layer	092899-666-B15, Roofing Material Main	Roof, Bottom Layer	
SLGL Lab#	135489		135490		135491		135492		135493		135494		

This Polarized Light Microscopy report relates only to items tested. Client should not use the NVLAP to claim endorsement. PLM by visual area estimation can produce errors of 10%. Results near the 1% level can be more accurately quantified by the point count method or Transmission Electron Microscopy. SLGL laboratory certifications apply only to samples analyzed in-house.

NVLAP Accrediatation Number 101228 Analytical Methodology: 600/R-93/116 July 1993

TTP = Test Till Positive

Martie cott, Lab Manager €~Ranald B. Sabin Analyzed By : Approved By:

The Sc t Lawson Group, Ltd. Environmental, Health & Safety Consultants

Report Prepared For:

Franklin NH 03235 428 Central Street Hill Mill Realty

29 River Road, Suite 18 FAX (603) 228-3871 Bow, NH 03304 (800) 645-7674

October 8, 1999 Report Date

999066 9/28/99 SLGL Job# Date Sampled

September 28, 1999 RAL Sampler Date Received

Beck Woolen Mill Client Project

Analyte: PLM/DS

Non Fibrous	Material	83	88 <	69<	89	89<	>74
	Other	!	1	1 1 1	i	!	:
us Material	Synthetic		1 1 1 2	1	1 1	$\overline{\vee}$	$\overline{\vee}$
Other Fibrous Material % Fibrous	Cellulose Synthetic Other	0.1	$\overline{\vee}$	30	-	30	10
Fibrous	Glass	2	$\overline{\vee}$	:	1	1	15
	Crocidolite		1	1 1 1	!	i	1
- Asbestos % -	Amosite	1	;		!	:	1
	Chrysotile Amosite Crocidolite	2	10	$\overline{\vee}$	10	$\overline{\vee}$	
Color		Black, White	Yes Yes Black, White	Black, Gray, White. Brown	Yes Black, Gray	Black, Brown, Grav	Black, White
Fibrous	conorda	Yes Yes	Yes	Yes	Yes	Yes	Yes
Obvious 1 avers	200000	Yes	Yes	Yes	Yes	Yes	Yes
Obvious Homogeneous Layers Fibrous		°N	No	No	No	Š	Š
Sample Description		Roof, Top Layer	092899-666-B17, Roofing Material, Main Roof, Flashing Tar	092899-666-B18, Roofing Material, Front Overhang, Main Layer	092899-666-B19, Roofing Material, Front Overhang, Bottom Layer	092899-666-B20, Roofing Material, Rear Overhang, Bottom Layer	092899-666-B21, Roofing Material, Rear Overhang, Top Layer
SLGL Lab#	135495		135496	135497	135498	135499	135500

produce errors of 10%. Results near the 1% level can be more accurately quantified by the point count method or Transmission Electron Microscopy. SLGL laboratory certifications apply only to samples analyzed in-house. This Polarized Light Microscopy report relates only to items tested. Client should not use the NVLAP to claim endorsement. PLM by visual area estimation can

NVLAP Accrediatation Number 101228 Analytical Methodology: 600/R-93/116 July 1993

TTP = Test Till Positive

L'ab Manager fit Ronald B. Sabin Analyzed By: -Approved By:

The Sco Lawson Group, Ltd. Environmental, Health & Safety Consultants

Report Prepared For:

Franklin NH 03235 428 Central Street Hill Mill Realty

29 River Road, Suite 18 FAX (603) 228-3871 Bow, NH 03304 (800) 645-7674

October 7, 1999 Report Date

September 28, 1999 999066 9/28/99 SLGL Job# Date Sampled Date Received

Sampler

RAL Beck Woolen Mill Storage Bldg. Client Project

Analyte : PLM/DS

			į				Ashestos %			10			
	1	Obvious Homogeneous Layers Fibrous	Obvious us Layers	Fibrous	Color	5	value in a		Fibrous	Fibrous Material %	us Material	%	Non Fibrous
A. Siding	092899-666-B22A. Siding Paper Front Side	1	;	;		Curysottle	Chrysottle Amosite Crocidolite	rocidolite	Glass	Cellulose	Cellulose Synthetic Other	Other	Material
Under Clapboards	t aper, a rolle side,	ON	Yes	Yes	Yes Yes Brown, Red	1	!	}	!	80	;	$\overline{\vee}$	>19
092899-666-B22B, Siding Under Clapboards	092899-666-B22B, Siding Paper, Front Side, Under Clapboards	No	Yes	Yes Yes	Brown, Gray	l		1 1 1	!	75	!	!	25
092899-666-B23, Cement B Interior, West End	092899-666-B23, Cement Board Panels, Interior, West End	No	Yes	Yes	Gray	35	1	ŀ	;	$\overline{\vee}$	!	1 1 1	>64
092899-666-B24, Roofing Min Burned Section	092899-666-B24, Roofing Material, Debris, in Burned Section	No	Yes	Yes	Yes Black	3	!	1	. !	30	1	!	19
092899-666-B25, Roofing Mon River Side of Building	092899-666-B25, Roofing Material, Debris, on River Side of Building	No	Yes	Yes	Black	4	}	1	;	12	_	1	83
Suspect De	092899-666-B26, Suspect Debris, Building Crawlspace	No	No	Š	No Gray	!	1	!!!!	1	$\overline{\vee}$		!	- 66<

This Polarized Light Microscopy report relates only to items tested. Client should not use the NVLAP to claim endorsement. PLM by visual area estimation can produce errors of 10%. Results near the 1% level can be more accurately quantified by the point count method or Transmission Electron Microscopy. SLGL laboratory certifications apply only to samples analyzed in-house.

NVLAP Accrediatation Number 101228 Analytical Methodology: 600/R-93/116 July 1993

TTP = Test Till Positive

Analyzed By: Kleffa M. Woll ame out Jennifer Scott, Lab Manager Approved By:

The Scc Lawson Group, Ltd.
Environmental, Health & Safety Consultants

Report Prepared For:

Hill Mill Realty 428 Central Street Franklin NH 03235

29 River Road, Suite 18 Bow, NH 03304 (800) 645-7674 FAX (603) 228-3871

Report Date: October 7, 1999

SLGL Job # : 990666 Date Sampled : 9/28/99

Date Received : September 28, 1999 Sampler : RAL

Sampler : RAL Client Project : Beck Woolen Mill Storage

Analyte : PLM/DS

			į				Achaetae						
Sample Description		Obvious Homogeneous I avers Eithann Color	Obvious Is I aware	City	Color		Aspestos % -	0,	Fibrous	Other Fibro	Other Fibrous Material % —	1	Non Cit
092899-666-B27A Window Glazing Birra		T. C.	to Layers	ribions	10100	Chrysotile	Amosite	Chrysotile Amosite Crocidolite Glass Cellulose Synthetic Other	Glass	Cellulose	Synthetic		Material
Side	icom Giazinig, Miver	o Z	Yes	Yes	Yes Yes White	4	1	-		:	1	⊽	>95
092899-666-B27B, Window Glazing, River Side	ndow Glazing, River	°	Yes	Yes	Yes Yes White	\$	!	!	;	ĺ	1	V	>94
092899-666-B28A, Flooring Paper, Interior, Center	oring Paper, Interior,	No	Š	Yes	No Yes Brown	-	;	1	l	75	!	. ;	36
092899-666-B28B, Flooring Paper, Interior Center	oring Paper, Interior	No	No	Yes	No Yes Brown	1		; ;	ł	80	; ; ;	! 6 3 8	20

This Polarized Light Microscopy report relates only to items tested. Client should not use the NVLAP to claim endorsement. PLM by visual area estimation can produce errors of 10%. Results near the 1% level can be more accurately quantified by the point count method or Transmission Electron Microscopy.

SLGL laboratory certifications apply only to samples analyzed in-house.

NVLAP Accrediatation Number 101228 Analytical Methodology: 600/R-93/116 July 1993

TTP = Test Till Positive

Analyzed By: Tluga M. Vaillame and

1

Approved By:

Jennifer Scott, Lab Manager

1									<u> </u>
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	The Scott Lawson Group, Ltd.	on Group, Ltd.	Company:	Real		# qor 757S	111 000 # qo		
1	Environmental, Health & Safety Consultants	k Safety Consultants	Attention:			Client	Client Project (24) 110 July 1111		
	29 River Road, Suite 18	Suite 18				Client PO:	ojear. Otal w		S-lorage Blog.
-	Bow, New Hampshire 03304 (603) 228-3610 Fax: (603) 228-3871	1pshire 03304	Address;	/3  8		Collected By:		O. Lent	
-	E-Mail: slgllab	@conknet.com					Matrix		
10	day 5 day D	leu.	Dhono 4.			A=	A= Air	0= Oil	
Conta	Contact Laboratory prior to requesting RUSH analysis	ng RUSH analysis	Fax #.			<b>∦</b>	W= Water S- Soil/Studes	E= Extract	
St.Gt. Lab #	Sample Identification				-	5	agnin singe	(À, other	
1264576	03.28	Analysis	ASIS	Date	Time Preservative	e 4°C Matrix	Media / Container	Air Volume	Minutes
	- 1	PLIM	(D5	75/		7	Rills		
	- B22 B					<	Jana -		
20	- 823							+	
S	ULB.			+		+	1	1	
				1					_
2 =	Bas					1			
	826								1
71	B27A			F				1	1
13	8728			+				1	1
<u> </u>					-	<u> </u>			
2	17 1848 17					1			
	N K Bas B					7		2	7
								>	8
Comments								180	
Soliniellis:			Relinquished By:		Time:	Accepted By	By:	300	į.
2	M Good Condition	( last		1 1/2/6	125pm m	mida (a)	Moun	7.	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
	Α	WHITE - Lahoraton					\ 		
			YELLOW - Results	ults	- NIII	- Client			1

# APPENDIX B

SAMPLE ANALYSIS RESULTS - LEAD

{solids.analyte}

Jennifer Scott, Lab Manager

The Scot awson Group, Ltd.

Environmental, Health & Safety Consultants

29 River Road, Suite 18

FAX (603) 228-3871 Bow, NH 03304 (800) 645-7674

428 Central Street Franklin NH 03235

Hill Mill Realty

Report Prepared For:

October 4, 1999 999066 9/28/99 Date Received Date Sampled Report Date SLGL Job#

September 28, 1999 MA Client Project Collected by

: Beck Woolen Mill

Lead Analyte

				Methodology : SW-846-6010	010
SLGL Lab#	Sample Description	mg/ko		Date	
	092899-666-L01, Green Paint, 1st Floor, Walls and Posts	9745	1.0	Analyzed 10/1/99	Analyst KDM
	092899-666-L02, Light Green Paint, 1st Floor, Wall	200	0.050	66/1/01	KDM
	092899-666-L03, Gray Paint, 1st Floor, North Wall	2532	0.25	66/1/01	KDM
	092899-666-L04, Brown/Black Paint, Boiler Room, Paint Covering Brick Walls	61403	6.1	66/1/01	KDM
	092899-666-L05, Red Paint, Outside, Paint of Building, Taken From East Side, Near Entrance	29903	3.0	66/1/01	KDM

All Analyses performed in accordance with U.S.E.P.A. Methods for Chemical Analysis of Water and Waste, EPA-600/4-79-020, Standard Methods for the Examination of Water and Wastewater or Test Methods for Evaluating Solid Waste, SW-846, or as otherwise noted. SLGL laboratory certifications apply only to samples analyzed in-house.

Reviewed By: \_

Approved By:

ND = None Detected

= Sample was analyzed outside of EPA holding time

= Less than

Minutes Time: Client Project: Berk Wallen Mil E= Extract <X= Other Date: Air Volume 0= Oil STOL Job# Matrix maga Collenna, S= Soil/Sludge BUIK 3 Media / Container W= Water Collected By: A= Air Client PO: Accepted By: 4°C Matrix PINK - Client Preservative Time 7.0 Time: 28 92899 Date Date: 0 YELLOW - Results Attention: Pract W W Phone #: Address: Relinquished By: Fax # Analysis LEAD WHITE - Laboratory 29 River Road, Suite 18
Bow, New Hampshire 03304
(603) 228-3610
Fax: (603) 228-3871
E-Mail: slgllab@conknet.com Contact Laboratory prior to requesting RUSH analysis Environmental, Health & Safety Consultants RUSH\_ In Cood Condition 107 505 203 3751 012899-666-Loi Sample Identification 5 day 10/2/99 results by (0 SLGL Lab# 9 Comments; 3

# APPENDIX C

SAMPLE ANALYSIS RESULTS - TCLP LEAD

The Scc Lawson Group, Ltd.

Environ....aral, Health & Safety Consultants
29 River Road, Suite 18

Report Prepared For:

Hill Mill Realty 428 Central Street Franklin NH 03235

-.ntal, Health & Safery Consultants 9 River Road, Suite 18 Bow, NH 03304 (800) 645-7674 FAX (603) 228-3871

Report Date : October 14, 1999 SLGL Job # : 990666

Date Sampled : 9/28/99
Date Received : September 28, 1999

Collected by : MA Extraction Date: 9/28/99

Client Project : Beck Woolen Mill

Sample : 092899-666-L01, Wood, Description From Demo Side of

Building

	Analyst KDM
)	Date Analyzed 10/5/99
	Detection Limit mg/L 0.020
	Regulatory Limit mg/L 5.0
	Result mg/L 115
	Methodology EPA 200.7
	Analyte Lead
	SLGL Lab# 135516-2

These samples were prepared by method SW-846-1311, TCLP. All analyses performed in accordance with U.S.E.P.A., SW-846 Methodology, Standard Methods for the examination of water or methods as stated. Units are in milligrams per liter or as noted. SLGL laboratory certifications apply only to samples analyzed in-house.

< = Less than

\* = Samples were analyzed outside of the EPA holding time

Reviewed By: Black of MCUT.

Approved By:

Jennifer Scott, Lab Manager

{TCLP}

UST Closure Report (NHDES, 2000)

				)		
Compe Ltd.	HILL Berry		SLGL JC	\$7.50 p #		
Attention	/		Client P	roject: Rac v	Client Project: Recommend to 11	
, ·			Client PO:	i i		
603) 228-3610 Fax: (603) 228-3871			Collected By:	. S.		
E-Mail: slgllab@conknet.com				Matrix		
10/2/01			A= Air		1	
Contact Laboratory prior to requesting RUSH analysis Fax #:			<b>X X</b>	W= Water S= Soil/Sludge /	E= Extract	
Analy	-		-	Media /	V- Oillel	
	Date	Preservative	4 C Matrix	Container	Air Volume	Minutes
	0 228	l	X	Ĺ	į	l
MODAL From Demo	5					
Side of Building 10 M. A. Ren MA			-			
1910			-			
			1			
					-	
					,	Ť
					1	T
			-			
			-			
1	Date: Time:		Accepted By:	By:	Date	Time.
Color Color	1/2/11/1/2/10	1600	1/01:0	Peng Vallemenu		0/281
WHITE - Laboratory					-	
randiatory YELLOW	- Results	PINK - Client	ient	-		Ī

## APPENDIX D

SAMPLING METHODOLOGY

#### SAMPLING METHODOLOGY

#### Samples for ACM:

A walkthrough of each area included in the survey was first conducted to determine the type and locations of suspect ACM. After this had been completed, *SLGL's* H&S Professional then proceeded to collect samples of the suspect materials and submit them to be analyzed for possible Asbestos content.

Suspect ACM was identified and categorized into homogeneous categories, if necessary. Homogeneous means uniformity in texture, color, and appearance. A typical sampling scenario during this project may have consisted of:

- 1. The inspector, equipped with appropriate protective equipment and sampling gear, moistens the area where the sample is to be collected. A wetting agent is added to prevent disturbance of the material and the release of fibers into the air.
- 2. The sample is extracted using a clean knife and/or tweezers. The inspector cuts a small piece of material penetrating all layers.
- 3. The sample is placed in a labeled container and sealed. The exterior of the container is then wet-wiped clean.
- 4. Sampling tools are cleaned and any fallen debris is cleaned with a High-Efficiency, Particulate Air (HEPA) vacuum.

Samples were then delivered to *SLGL's* laboratory for analysis. The samples were analyzed for possible Asbestos content utilizing the EPA Method 600/R-93/116, July 1993, which incorporates the use of Polarized Light Microscopy (PLM).

## Bulk samples for Lead:

Paint chip samples for Lead were collected by utilizing a knife or other sampling tool to collect a representative amount of suspect LBP. The samples were placed in labeled sample bags and sealed. Upon completion of the sample collection, the samples were returned to *SLGL's* American Industrial Hygiene Association-accredited (AIHA No. 342) laboratory and analyzed utilizing the appropriate Environmental Protection Agency (EPA) Method.

Composite samples for TCLP analysis were collected by obtaining a section of the entire thickness of the clapboard material, cutting it into smaller pieces and submitting the entire material to the laboratory for analysis (EPA Methodology 200.7).

Drum Inventory and Removal Action (NHDES/USEPA 1999-2000)

#### DEPARTMENT OF ENVIRONMENTAL SERVICES WASTE MANAGEMENT DIVISION WASTE MANAGEMENT COMPLIANCE BUREAU



#### ACTIVITY REPORT

Case No HWC 00-03

Case 110. 11 17 C 33-03	Confidential _ YES X NO
Date: 24 Feb 99 Time: 0910	Location: Hillsboro, NH
Division Staff: G. Carrigan, M. Galuszka, C. Fort	ier, T. Caligandes, D. Degler
Other Parties Name Affiliation Addre Alex Bottomly Property Manager	Tel. No. 464-0228
Tel. Comm Interview _x	Site Visit Other
Samples         x         NO         YES Sample           Photographs         NO         x         YES	No.

Confidential

#### SUMMARY OF ACTIVITIES

0910-Arrived at 25 West Mill, Street, Hillsboro, NH (Beck Mills) to await the arrival of Mr. Bottomly. Mr. Bottomly arrived at 0925. I explained to Mr. Bottomly that we wanted to assess the site for waste related issues. Based upon our observations, we might take some samples.

Mr. Bottomly has been the building caretaker for the past 11 years. He informed me that most of the drums were located on the first floor. Also, he said that asbestos could be found in the boiler room. He had worked on the maintaining and abating the asbestos in the past. Most of the asbestos is found in the boiler room and transite boards are located in the adjacent smaller building wharehouse).

After discussing the information that Mr. Bottomly provided with other SIS personnel, we started the assessment in the main building. On the first floor he took us into the boiler room, located on the east end of the building. There are two old coal fired boilers in this room, and a newer oil fired boiler. The two old boilers were very large, parts (superstructure) of which extend from the basement up to the third floor. The boilers and piping are covered with asbestosinsulation. Mr. Bottomly informed us that he had taken some of ACM and stored it in one of the old boilers. Several photographs were taken of the boilers.

Along the east wall of the building (first floor) we observed 128, five-gallon pails of roofing cement.

These pails were empty. On this floor we located a majority of the drums and other containers of concern. see the attached list and map.

After moving to the second floor, we split into two teams. Mr. Bottomly took Ms. Calligandes and me to the basement (lower level). In the lower level, he showed us the boilers, and the location of a large water storage tank. This tank was coated (insulated) with asbestos. This tank is approximately 7-8' in diameter and 18-20' in length. On the same end of the building as the boilers, we located several drums of lubricants and other chemicals (see list and map). Photographs were taken of the drums on the first and basement levels.

No other waste issues were identified on either the second or third floors by M. Galuszka or D. Degler.

Next, Mr. Bottomly took us to the adjacent building (wharehouse). At one time, the two buildings had

#### NHDES

been connected. Along the way he showed the location of an UST. He believes that the tank was installed in the late 70's, and may be 10,000 gallons in capacity. He had pumped as much fuel out of it as he could, burning the fuel in his own home heating system. He stated that there was about 3-4 inches of sludge left in the bottom of the tank, or an estimated 300 gallons of sludge. He believes that this sludge is left over from the #6 fuel once burned at the facility.

In the adjoining building he showed us an area (30'x30') that had been covered over with transite paneling (ACM). This paneling covers the ceiling and the walls. Many of the wall panels had been damaged/broken by vandals. Also, he showed us a stack of drums at one end of this building which we could not reach due to the collapsed roof. He stated that the drums were empty, as he had stacked them in this location.

After reviewing our findings, we decided to go back in the main building, label the drums and take information from them to be used to help determine their contents. It is our opinion that there are three current waste issues at the site. These are:

- 1. The asbestos containing material (A.C.M.),
- 2. The chemicals in the drums, and
- 3. The UST.

Prior to leaving the site, I explained these concerns to Mr. Bottomly. Mr. Bottomly told me to contact him if DES had any other questions.

1210-Secured from the site.

		Beck's Mill Container Inventory
Number	Size	Labeling/Content Information
<b>B-</b> 1	30-gal steel drum	Barclay Chemical Company, Watertown, MA. Volamine (volatile amine)
B-2	5-gal plastic pail	Wolfs Head Special Duty Oil, 15-40w
B-3	30-gal steel drum	NB-95, Nutmeg Chemical Corporation, New Haven, CT
B-4	30-gal steel drum	Black color drum, contents unknown
<b>B-</b> 5	5-gal plastic pail	Asphalt roof coating-spilled
B-6	55-gal steel drum	Empty
B-7	55-gal steel drum	Nutmeg Chemical Corporation, Fuel Oil Conditioner
B-8	-	Empty
B-9	55-gal steel drum	Petroleum waste, 1/4 full
B-10	-	Empty
B-11	-	Empty
B-12	55-gal steel drum	Black colored drum, no marking 3/4 full
1-1	55-gal steel drum	Labeled 'Lenospin', ½ full
1-2	55-gal fiber drum	Nopcotex 668, Diamond Shamrock Corporation, Process Chemical Division, 350 Mt. Kimble Ave., Morristown, NJ
1-3	55-gal steel drum	Label is covered (can not read) and drum is frozen to the floor
1-4	55-gal steel drum	Unknown
1-5	55-gal steel drum	Unknown
1-6	55-gal steel drum	Diamond Shamrock Corporation, 'Textilene 970F'

	-	Beck's Mill Container Inventory	
1-7	55-gal steel drum	Unknown	
1-8	55-gal steel drum	Believed to be Napxostat 2152-P (?)	
1-9	55-gal steel drum	Same as 1-8	
1-10	55-gal fiber drum	Diamond shamrock Corporation, Unknown	
1-11	55-gal steel drum	Unknown	
1-12	55-gal steel drum	Unknown	
1-13	55-gal steel drum	Same as 1-8	
1-14	55-gal steel drum	Same as 1-8	
1-15	15-gal plastic carboy	Believed to be a wool dye	
1-16	55-gal steel drum	Unknown	
1-17	55-gal steel drum	Unknown	
1-18	55-gal steel drum	Unknown	
1-19	55-gal steel drum	Textalene	
1-20	55-gal steel drum	Lenospin	
1-21	55-gal steel drum	Unknown	
1-22	5-gal plastic pail	Diamond Shamrock Corporation, ½ full	
1-23	55-gal steel drum	Texaco, oil (?)	
1-24	55-gal steel drum	Unknown	

Beck's Mill Container Inventory					
1-25	55-gal steel drum	Texaco, oil (?)			

:\hwc9903a.act

Wood Woolen Mill Drum Inventory

vvood vvoolen		ventory		
Drum Number		Contents	Comments	
1	55	Oil	no PCB's	MM
2	30	Alkaline Liquid	pH 12	EM
3	55	Oil	no PCB's	□ NN
4	55	Distillate	may be flammable	EPA
5	55	Oil	no PCB's	WH.
6	30	Organic Amine	Water Treatment Compound pH 11	- GPA
7	30	Alkaline Liquid	ph 11	Ega
8	55	Organic Liquid	Not oil non haz	CAR 4
9	55	Oil	no PCB's	MM
10	55	Oil	no PCB's	-NN
11	55	Grease		EA
12	55	Oil	no PCB's	NH
13	55	Oil	no PCB's	MK
14	55	Oil	no PCB's	NH
15	55	Oil	no PCB's	MM
16	55 .	Oil	no PCB's	MM
17	55	Oil	no PCB's	am
18	30	Grease	TIOT ODS	
19	55	Grease		EPA EPA
20	20p	Wax or Grease		
21	20p	Alkaline Liquid	pH 12	EPA
22	55	Oil	no PCB's	EPA
23	55	Oil & Water	HOPCBS	NK
24	55	Oil	no PCB's	MX
25	55	Inorganic Solid	non haz	N. W.
26	55	Oil	no PCB's	GPA
27	55	Wax or Grease	110 F CB S	NX
28	55	Aqueous Liquid	Probably water	699
29	55	Oil & Water	Probably water	EA
30	55	Oil	no DCD'o	KN
31	55	Oil	no PCB's	NA NA
32	55	Oil	no PCB's	-
33	55		no PCB's	KM
34	55	Aqueous Liquid	Probably water	EPA,
35	55	Oil & Water		end
36	UST	Organic Solid	non haz	EPA
37		Oil	no PCB's	NH E TANK
38	<b>55</b> 55	Oil & Water		MM
39	55	Oil & Water		MM
40 .	55	Oil & Water		M
41		Oil & Water		MM
42	55 55	MT		- neme white
	55	Water		n
43	55	Water		•>
44	55	MT		•}
45	55	Water		•
46	55	Water		•1
47	55	Water		al
48	55	Water		•
49	55	Oil & Water		KN
50	55	Water		LENE
51	55	Oil & Water	네 요요요 그래요 그렇게 들어가 요요요 그렇게 되는 것이 그 가지 않는데 가지 않는데 그렇게 되었다.	M
52	55	Water		LENE
53	55	Water	ľ	LEADE

NHDES NHDES HH HH HH

111



# DEPARTMENT OF ENVIRONMENTAL SERVICES

6 Hazen Drive, P.O. Box 95, Concord, NH 03302-0095 (603) 271-3644 FAX (603) 271-2181

March 22, 2001

Mr. Leon Griffin III 25 West Mill Street Hillsboro, NH 03244

SUBJECT: Hillsboro-Woods Mill Site,25 West Mill Street: Tank Closure Report,

February 8, 2001 by Ralph Wickson, HWRB. (UST #0115155)

(DES# 199909015)

Dear Mr. Griffin:

The New Hampshire Department of Environmental Services (DES) has reviewed the report for the December 26, 2000, tank closure by Ralph Wickson, HWRB for the 12,000 gallon fuel oil underground storage tank removed at the above referenced facility. Based upon the information contained in the report, DES has concluded that:

- It does not appear that a discharge of petroleum that would ultimately impact surface water or groundwater of the State has occurred from this tank. Therefore, DES will not require additional investigation or remedial measures related to this tank removal.
- 2. The owner(s) of this facility must meet the goals of the N.H. Administrative Rules Env-Wm-1403 "Groundwater Management and Groundwater Release Detection Permits", that is, groundwater at the site must continue to meet drinking water quality standards. The owner shall not undertake any activities which might result in Ambient Groundwater Quality Standards being exceeded at the site.

DES reserves the right, under N.H. Administrative Rules Env-Wm-1403 "Groundwater Management and Groundwater Release Permits" and N.H. Administrative Rules Env-Ws 412, "Rules for Reporting and Remediation of Oil Discharges," to require additional hydro-geological investigations and/or remedial measures, if further information indicating the need for such work becomes know.

If you have any questions, please contact me at the Waster Management Division at (603)-271-3644.

Charles Berube

Oil Remediation & Compliance Bureau

CB/gls:/h:\990915.301 cc: Ralph Wickson, HWRB Scott Pellerin, USEPA File

# STATE OF NEW HAMPSHIRE

280 Inter-Department Communication

FROM:

Ralph Wickson

Hazardous Waste Remediation Bureau

DATE: February 8, 2001

SUBJECT:

HILLSBORO – Woods Mill Site (Former Beck Mill Trust Property), Permanent Underground Storage Tank (UST) Closure Report for One Unregistered UST (DES #199909015 / UST I.D. #0-115155)

TO:

Thomas Beaulieu, Supervisor UST Compliance Section

Oil Remediation & Compliance Bureau

In accordance with Env-Wm 1401.18, Underground Storage Tank (UST) Closure Sampling & Reporting Guidelines, this memorandum serves to document findings regarding permanent closure (i.e., removal & off-site disposal) of one unregistered 12,000-gallon capacity UST at the subject property. Removal activities were conducted on December 22, & 26, 2000. This memorandum is intended to meet the requirements of Env-Wm 1401.18. The UST Closure Notification Form is attached (Attachment #1).

### I. Site Description

The subject property is identified as 25 West Mill Street, and is shown on the plan entitled, Small Sub-Division of Land of Woods Woolen Mill Co., Inc., Hillsborough, dated June 30, 1976, referenced at Book 4206, Page 34 of the Hillsborough County Registry of Deeds. The property consists of an abandoned wooden mill building and brick boiler room (circa 1900) situated immediately adjacent to the Contoocook River. The mill, which has not been active for a number of years, is currently in the process of being demolished.

The owner of record is:

Mr. Leon Griffin, III.
25 West Mill Street
Hillsboro, New Hampshire 03244

The single walled 12,000-gallon capacity UST was identified during an initial site evaluation in September 1999. The evaluation also identified a number of drums containing both hazardous and non-hazardous materials stored within the mill. The UST appeared to have been abandoned for an extended period of time. A figure detailing the location of the UST is attached to this memorandum (*Attachment II*). The Department's database did not include a record of the UST. However, the database did indicate the presence of a No. 2 Heating Oil UST closed in September 1998 (# 0-115155).

Tom Beaulieu Hillsboro – DES# 199909015 February 8, 2001 Page 2 of 2

A preliminary investigation of the UST indicated the presence of approximately 6 inches of oil and sludge (presumed to be weathered No. 6 Fuel Oil) within the tank. The tank contents were subsequently sampled to confirm the presence of No. 6 Fuel Oil.

#### II. UST Removal Action

In correspondence dated November 27, 2000, HWRB authorized the Department's clean-up contractor, Franklin Environmental, Inc. (Franklin), to proceed with removal of the non-hazardous drums and UST. Funding for this effort was provided by USEPA under Pollution Removal Funding Authorization No. B01500, issued to the Department on October 26, 2000. Franklin conducted the UST removal work on December 22, & 26, 2000. The work included: (1) confirmatory sampling of the oil/sludge within the UST to determine appropriate disposal method, (2) evacuation, utilizing a vacuum truck, and off-site disposal of 529 gallons of No. 6 fuel oil and sediment (the material was managed as non-hazardous State regulated oil waste), (3) excavation and off-site disposal of the UST, and (4) backfilling the excavation with 84 tons of clean sand fill to existing condition prior to excavation. Metal piping associated with the UST was also removed.

HWRB personnel provided oversight throughout the removal effort and collected soil samples from the excavation zone for on-site headspace screening (HNU). In addition, soil samples were collected from the excavation zone and submitted to the Department's laboratory for VOC, PAH, and TPH analysis in accordance with the requirements of Env-Wm 1401.18, Sampling & Reporting Guidelines (July 1999).

# III. Significant Findings

- No petroleum odor was evident in soil immediately above or below the UST.
- No positive PID (HNU) readings were observed during UST removal activities.
- Materials removed from the excavation consisted of medium brown to dark brown sandy soil with trace gravel and silt. The top 10 inches of soil was frozen.
- No free product or groundwater was encountered within the excavation;
- A localized area of stained soil, indicative of soil impacted by weathered fuel oil, was observed at the bottom of the excavation. Soil samples were collected from this area and other representative locations immediately beneath the tank and piping system for laboratory analysis in accordance with the requirements of Env-Wm 1401.18.

Tom Beaulieu Hillsboro – DES# 199909015 February 8, 2001 Page 3 of 3

The steel single walled UST measured 18' x 10'6". A visual inspection of the interior of the tank after removal of the oil and sediment indicated it to be in fair condition. The exterior of the tank was pitted and an approximately 1/4 inch hole was observed in the bottom center of the tank. Photographs taken during the UST removal activities are attached (Attachment III).

#### IV. Analytical Results

As indicated above, no positive PID readings were noted during UST closure activities. Composite soil samples (collected from five discrete locations within the excavation) were obtained in accordance with EPA Method 5035 for laboratory analysis following EPA Methods 8260B (VOC), 8270 (PAH), and 8015-DRO (TPH). No VOCs or PAHs were detected above laboratory quantification limits in the soil samples collected as part of this investigation. The TPH analysis indicated a concentration of 3,300 mg/kg of TPH as fuel oil. This concentration is below the NH S-1 standard of 10,000 mg/kg. Consequently, the soil samples collected for this effort exhibit compliance with RCMP soil standards. The laboratory reports for samples submitted for analysis are attached to this memorandum (*Attachment IV*).

#### V. UST Disposal

The UST carcass was shipped off-site for recycling as scrap steel. Invoices documenting all work performed by Franklin and all shipping manifests are contained in Department file #199909015.

Based on the above findings, no additional activities associated with this former UST are recommended. Should you have any questions or require additional information, please contact me at the HWRB at 6572.

F:\ust memo

Attachments (I - IV)


c: John Regan, HWRB (via e-mail)

File

New Hampshire Department of Environmental Services (603) 271-3644 FAX (603) 271-2181

## UST CLOSURE NOTIFICATION

1. Telephone Message		Initial	
Name		Date:	
Street		Telephone:	
City		Fax #	
Facility Registration Number:	Unregistered		
Name Former Woods Woolen Mi	11 (Beck Mill Trust)	Ciry Willah	
Street _25 West Mill Street			oro
Owner Name			3 8
Name Leon Griffin, III	City_Hillsboro	Telephone: (603)	464-4937
Tank Removal Information		uspected: R=Removal,	
X R AX L	R F L R		
Tank # <u>N/A</u> Tank #	[M] Deci (00.0)		
Size 12,000 Size	Size	Size	
Product Product	11	Product	· · · · · · · · · · · · · · · · · · ·
Will tank be replaced Will tank	be replaced Will tank be replace		
underground? Yes No underground	? Yes No underground? Yes		No underground? Yes No
Consultant / Contractor: DES /	Franklin Environmental		
Local Fire Dept. Notified Hills	hote Fin D	- 111C.	•
Local Fire Dept. Notified Hills	ANO FITE DEDLY		
Inspector R. Wickson		Date December	22 & 26, 2001
Field Screening Methods (tank and	l piping):		
Photo Ionization I	etector - Headspace Sa	mnling Technique	
ample Information		mbring recuirque	
tank # N/A tank #	tank #	tank #	
Soil 3 Water N/A Soil Water	Soil Water		tank #
Taken By: R. Wickson	10011 Water	Soil Water	Soil Water
ank Condition:			
tank # N/A tank #	· · ·	<del>-,</del>	6. 40
Pitting/Hole	tank#	tank #	tank #
ndicate tank and sample locations	by sketching on back of this	report. See Attac	hmont II
iclude photographs of the excavat	ion and tank(s) condition if	avaliable. See Attac	hment III
stimated cubic yards of stock pi	iled contaminated soil:		N/A cubic yards
Verification			
ave inspected the site of the removed tank chniques to determine regulated substance	(s), including the entire excavation	n area. I am knowledgab	le in field observation
hniques to determine regulated substance translation at the site. I have also inspected	contamination in soils and groun	water. There is no evide	nce of soil or groundwater
		no evidence of leakage.	- 50 - → 10 - 10 - 10 - 10 - 10 - 10 - 10 -
Signature:	1 1 7		Date:
CA	alon Weekso		1/31/01
AND THE RESERVE OF THE PROPERTY OF THE PROPERT			





# State of New Hampshire Department of Environmental Services 6 Hazen Drive • PO Box 95 • Concord, NH 03302-0095 (603) 271-3445/3446

Hillsboro - 199909015

### **Results of Laboratory Analysis**

S le #: A17779-1 Cacegory: IN HOUSE Matrix : Soil

Collection Date: 12/26/2000 13:00

Log in Date : 12/27/2000 Completion Date: 01/18/2001 Site : 19990915

Collectby : RALPH WICKSON

Locator : UST EXCAVATION COMPOSITE

Descript : Hazardous Waste

Account #: 05-06-05 Project #: 05-0029530

Analyte	Results	RDL	Analyte		
Dichlorodifluoromethane	BDL	280	Chloromethane	Results	
/inyl chloride	BDL	280	Bromomethane	BDL	280
Chloroethane	BDL	112		BDL	280
Diethyl ether	BDL	112	Trichlorofluoromethane	BDL	112
t,1-Dichleroethene	BDL	112	Acetone	BDL	560
Carbon disulfide	BDL	112	Methylene chloride	BDL	112
rans-1,2-Dichloroethene	BDL	112	Methyl-t-butyl ether	BDL	112
2-Butanone	BDL	560	1,1-Dichloroethane	BDL	112
is-1,2 Dichloroethene	BDL	112	2,2-Dichloropropane	BDL	112
romochloromethane	BDL	112	Chloroform	BDL	112
,1,1-Trichloroethane	BDL		Tetrahydrofuran (THF)	BDL	560
Carbon tetrachloride	BDL	112	1,1-Dichloropropene	BDL	112
Benzene	BDL	112 112	1,2-Dichloroethane	BDL	112
,2-Dichloropropane	BDL		Trichloroethene	BDL	112
ibromomethane	BDL	112	Dichlorobromomethane	BDL	112
is-1,3-Dichloropropene		112	4-Methyl-2-pentanone	BDL	560
rans-1,3-Dichloropropene	BDL	112	Toluene	BDL	112
-Hexanone	BDL	112	1,1,2-Trichloroethane	BDL	112
etrach oroethene	BDL BDL	1120	1,3-Dichloropropane	BDL	112
thy cibromide	BDL	112	Dibromochloromethane	BDL	112
,1, Cetrachloroethane		112	Chlorobenzene	BDL	112
/p-Xylenes	BDL	112	Ethylbenzene	BDL	112
tyrene	BDL	112	o-Xylene	BDL	112
sopropythenzene	BDL	112	Bromoform	BDL	112
,2,3-Trichloropropane	BDL	112	1,1,2,2-Tetrachloroethane	BDL	112
comobenzene	BDL	112	n-Propylbenzene	BDL	112
-Chlorotoluene	BDL	112	1,3,5-Trimethylbenzene	BDL	112
ert-Butylbenzene	BDL	112	p-Chlorotoluene	BDL	112
c-Butylbenzene	BDL	112	1,2,4-Trimethylbenzene	BDL	112
3-Dichlorobenzene	BDL	112	p-Isopropyltoluene	BDL	112
Butylberzene	BDI.	112	1,4-Dichlorobenzene	BDL	112
2-Dibiomo-3-chloropropane	BDL	112	1,2-Dichlorobenzene	BDL	112
exachlorobutadiene	BDL	112	1,2,4-Trichlorobenzene	BDL	112
2,3-Trichlorobenzene	BDL	112	Naphthalene	BDL	280
z, o il tenioropenzene	BUL	112			
			2000 DOMEST TO SERVICE		

A Method : SW-8260 Units: ug/kg

ient's Comments: WOODS MILL SITE

alyst Comments: Results reported on a dry wt basis. % solids = 90 %.

asure date: 28-DEC-00

Authorized Signature:

= milligrams per Liter

see Then

: Jess Than

L

11

ico Curies per Liter

cing Detection Limit

ug/L = microstans per Liter

BDL = Below Detection Limit

mg/kg = milligrams per Kilogram

MCL=Maximum Contaminent Level

> = Greater Than

ug/kg = micrograms per Kilogram

P-A = Present/Absent

J =Approximate Level



#### State of New Hampshire Department of Environmental Services 6 Hazen Drive • PO Box 95 • Concord, NH 03302-0095 (603) 271-3445/3446

19990901 Hills12000

Results of Laboratory Analysis

3ample #: A17779-2

gory: IN HOUSE

Macrix : Soil

Collection Date: 12/26/2000 13:00 og in Date : 12/27/2000 09:29

Completion Date: 01/18/2001

Locator : UST EXCAVATION COMPOSITE

Descript: Hazardous Waste

: 19990915

Collectby : RALPH WICKSON

Account #: 05-06-05 Project #: 05-0029530

Analyte ?-Methylnaphthalene Acenaphthene Acenaphthylene Anthracene Benzo(a) anthracene Benzo(b) fluoranthene Benzo(b) fluoranthene Benzo(k) fluoranthene Benzo(k) fluoranthene Intysene Dibenz(a,h) anthracene Iluoranthene Iluorene Indeno(1,2,3-cd) pyrene Iaphthalene Phenanthrene Indeno(1,2,3-cd)	Results ND	Units RDL EPA Method  ug/kg Dry 270  ug/kg Dry 270	***************************************
yrene 'yrene	ND	ug/kg Dry 270 ug/kg Dry 270	

T it's Comments: WOODS MILL SITE

nalyst Comments: ANALYSIS BY AMRO ENVIRONMENTAL LABORATORIES CORP; #0012289

eport Comments: METHOD: SW8270C. RESULTS AS DRY WEIGHT, 8.8% MOISTURE.

easure date: 04-JAN-01

/L = milligrams per Liter

i/L = pico Curies per Liter

L = Reporting Detection Limit

= Less Than

Authorized Signature:

ug/L = micrograms per Liter BDL = Below Detection Limit

mg/kg = milligrams per Kilogram

= Greater Than

ug/kg = micrograms per Kilogram

P-A = Present/Absent



#### State of New Hampshire Department of Environmental Services 6 Hazen Drive • PO Box 95 • Concord, NH 03302-0095 (603) 271-3445/3446

#### Results of Laboratory Analysis

Sample #: A18712-1

rix : Soil

: IN HOUSE \_ent

:199900015

Locator : UST EXCAVATION COMPOSITE

Collectby : Ralph Wickson Descript : WOODS MILL SITE

Log in Date: 01/23/2001 14:37

Collection Date: 12/26/2000 13:00 Completion Date: 02/08/2001

Analyte

Results

Units Acceptable Level

TPH (Fuel)

3800

mg/kg Dry

Extraction

Client's Comments: sub'd to AMRO

Analyst Comments: ANALYSIS BY AMMRO ENVIRONMENTAL LAB CORP; #0101194-01A

Report Comments: METHOD:SW8015B. SAMPLE RUN 21 DAYS OVER HOLD TIME PER CLIENT RE

Measure date: 31-JAN-01

Authorized Signature;

mg/L = milligrams per Liter ug/L = micrograms per Liter / > = Greater Than

< = Less Than

P-A = Present/Absent

BDL = Below Detection Limit ug/kg = micrograms per Kilogram

pCi/L = pico Curies per Liter

mg/kg = milligrams per Kilogram

RDL = Reporting Detection Limit MCL = Maximum Contaminent Level

C" '.00mL = Counts per 100 milliliters

ACM Sampling and Removal Action (2000-2001)

#### MEMORANDUM

Date:

October 23, 2000

From:

Steve Cullinane, DES, ARD

To:

Ralph Wickson, DES, WMD John Regan, DES, WMD

Subject:

Boiler Asbestos Samples, Woods Mill, Hillsboro

Ralph, John:

I have received verbal confirmation from the lab, that samples of suspect asbestos containing material collected from the two brick boilers are positive. The material is an insulating material that was extracted from behind the steel faceplates on both boilers. The material is 50% chrysotile asbestos, and is very friable. Based on my experience, I would expect to find a layer of this material behind the entire faceplate (10'x10'), most likely around the steel steam drums, and up high under the brick cap. Any brick and mortar that is in contact with this material would be difficult to clean, and therefore would also be treated as asbestos waste.

The rest of the samples are still being analyzed. I will forward the results when I get them.

Rec. ved 28-160-0.

Woods Woolen Mill, Hillsboro Boiler Asbestos Sampling October 16, 2000

Notor	6000			all poor in the control of the contr			×		Chrysofile		
% Asbestos	<u> </u>	o	20 2	3 0	0	0	0	0	20	0	
Description	Package Boiler Door Insulation	Center Boiler, Fire Brick	Center Boiler, Insulation Behind Steel Face	Center Boiler, Mortar between Brick layers, Left side.	Center Boiler, Mortar around sight glass hole, Left side.	Center Boiler,insulation from pipe hole, Back side	Side Boiler, inner packing around drum end.	Side Boiler, Fire Brick from rear of boiler	Side Boiler, Insulation Behind Steel Face	Side Boiler, Insulation in Brick sidewall, left side	er 16, 2000
Sample #	#1	#2	(#3	<b>7</b> #	9#	9#	2#		6#	#10	Date Sampled: October 10 Sampler: Steve Cullipane

Sampler, Steve Cullinane

Date Analyzed: Analysis By: Scott LawsonGroup, Ltd.

WOODS MILL HILLSBORD

Report Prepared For:

NH DES Air Resources Division Concord NH 03301 6 Hazen Drive

29 River Road, Suite 18

FAX (603) 228-3871 Bow, NH 03304 (800) 645-7674

October 24, 2000 Report Date

2051606 10/16/00 SLGL Job# Date Sampled

October 16, 2000 Sampler Date Received

Wood Mills - Hillsboro Steve Cullinane Client Project

Analyte : PLM

		Non Fibrous	Material	29	
	- %		Other	;	
	Material		ynthetic	1	
	er Fibrous	of the term	ciluiose S	-	
	Other Fibrous Material %	Shores C	Class	70	
		, atilohi	THE PARTY OF THE P	1 5 0	
	Asbestos %	Chrysotile Amosite Crocidolite	3	!	
	- Asbe	otile Amo			
		Chryse		i	
	Obvious	riomogeneous Layers Fibrous Color	Z	ivo res res brown, Black	
	Sample Description	#10 0:1- 10 ::	"10 - Side Boiler, Insulation Brick Side	Wall	2
ļ	SLGL Lab#	152444	1		

Analyzed By:

not use the NVLAP to claim endorsement. PLM by visual area estimation can produce errors of 10%. Results near the 1% level can be more accurately quantified

SLGL laboratory certifications apply only to samples analyzed in-house.

Analytical Methodology: 600/R-93/116 July 1993

NVLAP Accreditation Number 101228

by the point count method or Transmission Electron Microscopy.

This Polarized Light Microscopy report relates only to items tested. Client should

TTP = Test Till Positive

Ronald B. Sabin

Approved By:

ق

Jennifer Scott, Lab Manager

(Asb. Bulk)

The wort Lawson Group, Ltd. Environmental, Health & Safety Consultants

29 River Road, Suite 18 Bow, NH 03304

NH DES Air Resources Division

Report Prepared For:

Concord NH 03301

6 Hazen Drive

(800) 645-7674 FAX (603) 228-3871

October 20, 2000 2051606 Report Date SLGL Job#

October 16, 2000 10/16/00 Date Sampled Date Received

Wood Mills - Hillsboro Steve Cullinane Sampler Client Project

Analyte: PLM

	¥0												
SLGL Lab#	SLGL Lab# Sample Description	:	Obvious		0.00	4	Asbestos %	1	ō	ther Fibrou	Other Fibrous Material %	1	
157475		Homogeneous Layers Fibrous	Layers	Fibrous	Color	Chrysotile	Amosite (	Chrysotile Amosite Crocidolita	riprous				Non Fil
122433	#1 - Package Boiler, Door Insulation		M	1	ı			CICATORILE	Olass	Cellulose	Olass Cellulose Synthetic Other	Other	Mate
			ON	0 0 0	No No Brown, Black, Cream	1	1	: : :	:	İ	:	į	10
152437	#3 - Center Boiler Inculation	;											
	correct Policy, illouration	°Z	Yes	Yes	Yes Yes Gray, Black	50							į
152443	#9 - Side Boiles Issuelation of the							9	0 0	:	3 5 5	t 1 0	5
	Flue	°Z	Xes	Yes	Yes Yes Brown, Black,	20		į		$\overline{\vee}$			7
					White				•	;		1 5 8	7

TTP = Test Till Positive

This Polarized Light Microscopy report relates only to items tested. Client should not use the NVLAP to claim endorsement. PLM by visual area estimation can produce errors of 10%. Results near the 1% level can be more accurately quantified by the point count method or Transmission Electron Microscopy.

SLGL laboratory certifications apply only to samples analyzed in-house.

Analytical Methodology: 600/R-93/116 July 1993 NVLAP Accreditation Number 101228

Ronald B. Sabin Analyzed By: Approved By:

NH DES Air Resources Division Concord NH 03301 6 Hazen Drive

29 River Road, Suite 18 Bow, NH 03304 (800) 645-7674 FAX (603) 228-3871

October 24, 2000 Report Date

2051606 10/16/00 SLGL Job# Date Sampled

October 16, 2000 Sampler Date Received

Wood Mills - Hillsboro Steve Cullinane Client Project

Analyte : PLM

SLGL Lab#	Sample Description	Homography	Obvious				- Asbestos % -	%		Other Fibrous Material %	us Material	%	
152436	#2 - Center Boiler Fire Brick	TOTAL LAYERS Fibrous Color	s Layers	Fibrous		Chrysotile	Amosite	Chrysotile Amosite Crocidolite	Glass	Glass Cellulose Synthetic Other	Synthetic	Other	Non Fibi Materi
(3) (3) (3)	WOLLD ON THE CONTRACT	No No	Yes	Yes	Yes Yes Tan, Cream, Brown	l	9	į	1 1	⊽		:	>9
152438	#4 - Center Boiler, Masonry	No	Yes	No	Yes No Brown, Black	į	į	1					
152439	#5 - Center Boiler, Masonry Layer	No	Yes	Yes	Yes Cream, Brown,	;	- [	!	1	$\overline{\nabla}$	İ	:	01
152440	#6 - Center Boiler Insulation	2	;		Tan					7		;	8
152441	#7 - Side Boiler Dacking I1.	ON	o N	Yes	Yes Black, Red, Gray	-	1	!	i	$\overline{\vee}$	40	2	>57
	Around Drum	o N	Š	Yes	Yes Brown, Gray	į	ł	:	70	į	1	1 1 2 8	30
152442	#8 - Side Boiler, Fire Brick	No	Yes	No No	No Cream, Brown.	1							
)					Gray, Black			9 9 2		1	1 1 7	!	100

TTP = Test Till Positive

not use the NVLAP to claim endorsement. PLM by visual area estimation can produce errors of 10%. Results near the 1% level can be more accurately quantified This Polarized Light Microscopy report relates only to items tested. Client should by the point count method or Transmission Electron Microscopy.

Analyzed By:

Approved By:

SLGL laboratory certifications apply only to samples analyzed in-house.

Analytical Methodology: 600/R-93/116 July 1993 NVLAP Accreditation Number 101228

Jennifer Scott, Lab Manager

(Asb. Bulk)

C HO-1108 H0-110X Row State Main



## State of New Hampshire DEPARTMENT OF ENVIRONMENTAL SERVICES

6 Hazen Drive, P.O. Box 95, Concord, NH 03302-0095 (603) 271-2900 FAX (603) 271-2456



August 11, 2000

Mr. Gary Lipson, On-Scene Coordinator US EPA Region 1 1 Congress Street, Suite 1100 Boston, MA 02114-2023

SUBJECT: Woods Woolen Mill Asbestos Removal, Hillsborough, New Hampshire

Dear Mr. Lipson:

This letter is sent in response to your telephone conversation held on August 3, 2000 with Mr. Ralph Wickson of the New Hampshire Department of Environmental Services (Department) in regards to the Subject project. In regards to your inquiry as to whether or not the asbestos removed from the Woods Woolen Mill, located off West Mill Street in Hillsborough, New Hampshire, could be disposed of at the Town of Hillsborough's (Town) Landfill, located off Dump Road, the Department offers the following:

The Town's landfill can be used as a disposal location for the asbestos removed from the Woods Woolen Mill. It is the Department's understanding that Weston & Sampson, consultant on behalf of the Town, is preparing the necessary asbestos disposal plan. The plan must include the proposed location for disposal within the landfill footprint. Upon completion of the disposal, an as-built plan identifying the location of the asbestos is to be provided to the Department.

If there are any questions regarding this letter, or if you would like to arrange to meet with Department personnel, please contact me at (603) 271-2925.

Sincerely,

David J. Rousseau, Supervisor Solid Waste Compliance Section

DJR/Woods Woolen Mill, Hillsborough

Richard S. Reed, Administrator, NHDES SWMB

Ralph Wickson, NHDES Steve Cullinane, NHDES, ARD

James Coffey, Business Administrator, Hillsborough

J. Hutchins, P.E., Weston & Sampson

Town of Hillsborough Solid Waste File/DB

AUG 1 4 2000

DEPARTMENT OF FAVIOUS PRINCES

TDD Access: Relay NH 1-800-735-2964

http://www.state.nh.us